CERTIFICATE OF ANALYSIS

Milbank Manufacturing Company

1400 E. Havens P.O. Box 754

Kokomo, IN 46903-0754 Attn: Ronda S. Yeakley

Purchase Order: 206941

Invoice Number:

Order #: 98-02-370 Date: 02/16/98 14:27

Work ID: Effluent Water Composite

Date Received: 02/13/98
Date Completed: 02/16/98

Client Code: MILBANK MFG

SAMPLE IDENTIFICATION

Sample Number Sample

Description

Effluent Water Composite

Sample

Sample

Number

Description

This report may not be reproduced except in full, without the written approval of the laboratory. All results relate only

to the items tested.

This report contains a total number of pages: 02

Certified By



Order # 98-02-370 02/16/98 14:27

TEST RESULTS BY SAMPLE

Sample: 01AW Effluent Water Composite Collected: 02/12/98 Category: WATER

Test Description	Result	<u>Limit</u>	Units	Analyzed	Ву
Iron, ICAPES	0.504	0.010	mg/L	02/16/98	JAR
Lead, ICAPES	<0.040	0.040	mg/L	02/16/98	JAR
Silver, ICAPES	<0.010	0.010	mg/L	02/16/98	JAR
Zinc, ICAPES	9.360	0.010	mg/L	02/16/98	JAR



5933 West 71" Street * Indianapolis, IN 46278 Phone (317) 290-1471 * Fax (317) 290-1670

CHAIN OF CUSTODY RECORD

Project	Rame: ////////////////////////////////////	ire:	Project	In			Total Number of Containers	Preser	d (Y or v. Code	/	7						Comments	Preservation Codes: A = Acld B = Base C = Cool 4°
	2-12-98		×		Effluent	PIT	/	7										
						4					,							
															2.74			
													,					
								x***										
								-										
							<u>.</u>											
							<u>'</u>											
																	· ·	
Relinquished By: Date / Time Received By: Da Lante Cala 2-13-58 Lante Cala 2-13-58 Lante Cala 2-13-58			ate / Time / 845 / 3	e Additional Information: Turn Around Time: Normal Rush Report Due:														
			ate / Time	Are samples suspected to be: Flammable Corrosive Toxic										Toxic 🔲				
						Were samples received intact and properly preserved? Yes No									No 🗀			
Relinqui	shed By:	,	Date /	Time	Received By:	D	até / Time		Temp.	. Blanl		"C						